

TIFFIN MOTORHOMES, INC.

RETAIL PRICE LIST

2007 Allegro

Fred Allegro			32 BA Fred	34 WA Fred	34 TGA Fred	35 TSA Fred
			\$112,259	\$115,059	\$118,349	\$120,470
<i>Chassis</i>	28 DA	30 DA	32 BA	34 WA	34 TGA	35 TSA
Ford (20,500 GVWR)	\$90,580	\$92,939	\$94,199	\$96,999		N/A
Workhorse (20,700 GVWR)	N/A	\$98,119	\$99,659	\$102,179		N/A
Ford (22,000 GVWR, 19.5" Wheels and Tires)	N/A	N/A	N/A	N/A	\$109,359	\$102,410
Workhorse (22,000 GVWR, 19.5" Wheels and Tires)	N/A	N/A	N/A	N/A	\$105,189	\$108,470
<i>Driftwood Exterior</i>	N/C	N/C	N/C	N/C		N/C
<i>Exterior #2- TBD</i>	N/C	N/C	N/C	N/C		N/C
<i>Stone Interior</i>	N/C	N/C	N/C	N/C		N/C
<i>Beach Glass Interior</i>	N/C	N/C	N/C	N/C		N/C
<i>Mirage Interior</i>	N/C	N/C	N/C	N/C		N/C
<i>Medium Alderwood Cabinetry (Std)</i>	N/C	N/C	N/C	N/C		N/C
<i>Natural Maple Cabinetry</i>	\$980	\$980	\$980	\$980		\$980
<i>Cherry Bark Cabinetry</i>	\$980	\$980	\$980	\$980		\$980
5.5 Onan Generator	\$580	\$580	\$580	\$580		\$580
7.0 Onan Generator	\$1,120	\$1,120	\$1,120	\$1,120		\$1,120
Drivers Door w/ Power Window	\$980	\$980	\$980	\$980		\$980
Semi-Automatic King Dome Satellite	\$910	\$910	\$910	\$910		\$910
2nd 13,500 Air Conditioner (Rear)	\$679	\$679	\$679	\$679		\$679
(1) 15,000 A/C w/ Heat Pump IPO 13,500 (Frt Only)	\$490	\$490	\$490	\$490		\$490
<i>Side View Cameras- Activated w/ Turn Signals</i>	\$630	\$630	\$630	\$630		\$630
CB Antenna	\$70	\$70	\$70	\$70		\$70
DVD Player (Living Room)	\$245	\$245	\$245	\$245		\$245
Power Driver Seat	\$420	\$420	\$420	\$420		\$420
Convection Microwave	\$693	\$693	\$693	\$693		\$693
Vacuum Cleaner System	\$350	\$350	\$350	\$350		\$350
Hide-A-Bed	N/A	N/A	\$660	\$660		\$660
Sofa IPO Booth Dinette	\$910	N/A	N/A	N/A		N/A
Ice Maker in Refrigerator	\$336	\$336	\$336	\$336		\$336
Refrigerator Inserts- Wood Panels	\$350	\$350	\$350	\$350		\$350
Additional Fantastic Fan (Water Closet Only)	\$280	\$280	\$280	\$280		\$280
Bedroom TV	\$455	\$455	\$455	\$455		\$455
Bedroom Day/ Night Shades- ea.	\$91	\$91	\$91	\$91		\$91
Washer/ Dryer	N/A	N/A	N/A	\$1,200		N/A

Certain Options Are Not Available On All Models!